

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**






Figure 1

Figure 2



### Figure 3




Guidry + Morales  
Feb 14. 00

Top plan view of a rectangular frame assembly 100. The assembly includes a central rectangular frame 34 with four corner brackets 5 and 6. The frame is defined by dashed lines. Dimensions include a total width of 26 1/2" and a total height of 31 1/2". A central horizontal section is 4 7/8" high, and a central vertical section is 3" high. A central rectangular opening 44 is shown with a diagonal dimension of 13 7/16". Other dimensions include 2 7/8" for the top corner bracket, 17 7/8" for the top corner bracket, and 23" for the top corner bracket. The frame is labeled 34, and the corner brackets are labeled 5 and 6. The central opening is labeled 44. The frame is also labeled 100.


## Figure 4

Guidry & Morales  
Bo. Thom 19.00




**Figure 5A**

**Figure 5**




*Guidry + Morales (Front View)*



SPILL PAN DRAIN

OUTLET DETAIL



**Figure 7**  
COUPLING DETAIL

**Figure 6**

Gundry & Morales (valve outlet view)



Guidry & Morales  
Baffle Detail